



Photo 1 – View of wreckage from first point of impact (courtesy of witness)



Photo 2 – Fuselage and empennage at accident site (courtesy of witness)



Photo 3 – Right and portion of left wing at accident site (courtesy of witness)