

On Scene Photos
Courtesy of Western Helicopters



Figure 1: Overview of Debris Path

On Scene Photos
Courtesy of Western Helicopters



Figure 2: Tail Rotor Blade from Above

On Scene Photos
Courtesy of Western Helicopters



Figure 3: Close up of Tail Rotor Blade

On Scene Photos
Courtesy of Western Helicopters



Figure 4: Tail Rotor Blade

On Scene Photos
Courtesy of Western Helicopters



Figure 5: Main Rotor Blade Fragment Location

On Scene Photos
Courtesy of Western Helicopters



Figure 6: Main Rotor Blade Fragment

On Scene Photos
Courtesy of Western Helicopters



Figure 7: Debris Path from Main Rotor Blade Fragment

On Scene Photos
Courtesy of Western Helicopters



Figure 8: Debris Path in Relation to Damaged Trees

On Scene Photos
Courtesy of Western Helicopters



Figure 9: Damaged Trees Above the Main Wreckage

On Scene Photos
Courtesy of Western Helicopters



Figure 10: Overview of Helicopter

On Scene Photos
Courtesy of Western Helicopters



Figure 11: Underside of Fuselage

On Scene Photos
Courtesy of Western Helicopters



Figure 12: Overview of Tail Boom

On Scene Photos
Courtesy of Western Helicopters



Figure 13: End of Tail boom

END.
Submitted by: Samantha Link