



RECORD OF CONVERSATION

Samantha Link
Aviation Accident Investigator
Western Pacific Region

Date: March 31, 2022
Person Contacted: Mr. Frank Motter (FAA Inspector)
NTSB Accident Number: WPR20LA237

Narrative:

During a telephone conversation, Mr. Motter reported the following:

The airplane went through the roof of a building about 350 yards southwest of the runway. The airplane entered the roof, went through a wall, and came to rest on top of a second wall. The wings were bent aft; and the left wing was lower than the right. The aft fuselage and empennage extended upward and remained above the roofline. Mr. Motter provided the below map.




Figure 1: Airplane in Relation to the Runway

END. Submitted by: Samantha Link