


01/11/2020

~15 min flight at the manufacturer.

Data from the LX9000



06/20/2020

~6 min flight at Lampson Field Airport, Lakeport, California. (FES was shutdown on ascent and uncommand FES start in flight followed by unusual landing)

Data from the LX9000

(ADS-B data for this flight was not found)




Figure 2-Flight track.

7/12/2020

~4 hr 15 min flight at Air Sailing Gliderport, Sparks, Nevada.

Data from the LX9000

(ADS-B data for this flight was intermittent.)




Figure 3-Flight track.

07/21/2020

~17 min flight at Lampson Field Airport, Lakeport, California.

Data from the LX9000

(ADS-B data for this flight was not found)




Figure 4-Flight track.

08/07/2020- (Accident Flight)

~20 min flight at Lampson Field Airport, Lakeport, California

Data from the LX9000 (file incomplete)

(ADS-B data for this flight was not found)





Figure 5-Flight track.

08/07/2020 (Accident Flight)

~20 min flight at Lampson Field Airport, Lakeport, California

Data from the Powermouse (completed file)

(ADS-B data for this flight was not found)



08/07/2020 (Accident Flight)

~20 min flight at Lampson Field Airport, Lakeport, California

Data from Powermouse (completed file) viewed on SeeYou website.

(ADS-B data for this flight was not found)

