



Photo 1 – N314 at the accident site. Photo courtesy of the Operator.



Photo 2 – Top view. Photo Operator.




Photo 3 – Underside view. Photo Operator.



Photo 4 – Wreckage at the recovery site.



Photo 5 – Engine, left view. Photo Operator.




Photo 6 – Engine, right view. Photo Operator.



Photo 7 – Right pylon.



Photo 8 – Left pylon.




Photo 9 – Left-side rotor blades. Red blade is on the left, and the white blade in on the right.




Photo 10 – Left-side, white rotor blade servo flap assembly.




Photo 11 – Right-side white rotor blade as seen from the tip end.



Photo 12 – Right-side white rotor blade, as seen from the root end.



Photo 13 – Right-side red rotor blade, as seen from the root end.




Photo 14 – Right-side red rotor blade, as seen from the tip end.




Photo 15 – Long line.




Photo 16 – Google Earth image with Onboard GPS data.



Photo 17 – Accident helicopter. Source Central Copters