



Photo 1 – View of damage to N93AB (Courtesy of Law Enforcement)



Photo 2 – Post-accident view of left trim surface (Courtesy of Law Enforcement)



Photo 3 – Post-accident view of right trim surface (Courtesy of Law Enforcement)