



**Photo 1 –N509CG, Top view, showing man rotor blade damage. Photo courtesy of the pilot.**



**Photo 2 – N509CG, Bottom view, showing damage to the lower-right fuselage. Photo courtesy of the pilot.**



**Photo 3 – N509CG, top view, showing main rotor blade damage. Photo courtesy of the pilot.**



**Photo 4 – N509CG, Rear view, showing damage to the tail boom. Photo courtesy of the pilot.**