



RECORD OF EMAIL

Samantha Link
Aviation Accident Investigator
Western Pacific Region

Date: October 22, 2020
Person Contacted: Mr. Lawrence Tolentino (Federal Aviation Administration)
NTSB Accident Number: WPR21LA017

Narrative:

Mr. Tolentino reported that he spoke with the certified flight instructor and confirmed that he did not activate the carburetor heat when the engine started to sputter.

END.

Submitted by: Samantha Link