



Photo 1 – Accident site.



Photo 2 - Cabin area, with wood grip installed on the control column.



Photo 3 – Cabin area, with wood grip separated from control column.



Photo 4 - Cabin area, with wood grip separated from control column.