



Photo 1 – N755MG, showing substantial damage to the right-wing strut. Photo courtesy of the Operator