



Photo 1 – View of the failed carry through (Courtesy of Pilot)



Photo 2 – View of damage to the composite empennage (Courtesy of Pilot)