



Photo 1 – N109EX, front and underside view. Photo courtesy of the Operator.



Photo 2 -Rear view. Photo courtesy of the operator.



Photo 3 – Left side view. Photo courtesy of the recovery agent.



Photo 4 – Left-rear view. Photo courtesy of the recovery agent.



Photo 5 – Tail rotor and 90-degrees gearbox. Photo courtesy of the operator.



Photo 6 – Tail rotor assembly and 90-degrees gearbox. Photo courtesy of the operator.