



Photo 1 – View of runway trench which the left wheel struck during an attempted go around (courtesy of the operator)