



Photo 1 – View of substantial damage sustained to the right wing and wing lift strut (Courtesy of FAA)