



Photo 1 – Top view, showing damage to the tail boom. Photo courtesy of the operator.