



Photo 1 – Underside view of the right wing showing substantial damage. Photo courtesy of the operator.



Photo 2 – View of the failed landing gear strut. Photo courtesy of the operator