



Photo 1 – Quartering view of accident airplane (Courtesy of Federal Aviation Administration)



Photo 2 – View from right wing (Courtesy of Federal Aviation Administration)



Photo 3 – Cylinder no. 3 connecting rod shaft fracture at accident site (Courtesy of Federal Aviation Administration)