



Photo 1 – Accident site, southeast view of the main wreckage. (Courtesy of the Lemhi County Sheriff's Office)



Photo 2 – Accident site, east view of the main wreckage. (Courtesy of the Lemhi County Sheriff's Office)



Photo 3 – Accident site, northeast view of the main wreckage. (Courtesy of the Lemhi County Sheriff's Office)



Photo 4 – Accident site, right horizontal stabilizer and elevator. (Courtesy of the Lemhi County Sheriff's Office)



Photo 5 – Accident site, left horizontal stabilizer and elevator. (Courtesy of the Lemhi County Sheriff's Office)



Photo 6 – Accident site, left main landing gear brake assembly. (Courtesy of the Lemhi County Sheriff's Office)



Photo 7 – Accident site, first identified contact with the runway. (Courtesy of the Lemhi County Sheriff's Office)