



Photo 1 – Left side of airplane with missing door (Courtesy of Federal Aviation Administration)



Photo 2 – Left horizontal stabilizer (Courtesy of Federal Aviation Administration)



Photo 3 – Door crank interior assembly (Courtesy of Lancair Owners and Builders Association)