



Photo 1 – View of damage to the lower fuselage forward bulkheads and stringer (Courtesy of FAA)