



Photo 1 – Left side view of fuselage damage (photo courtesy of the NTSB)



Photo 2 - Left side view of fuselage damage (photo courtesy of the NTSB)



Photo 3 - Right side view of fuselage damage (photo courtesy of the NTSB)



Photo 4 - Right side view of fuselage damage (photo courtesy of the NTSB)




Photo 5 - View of tooling marks on fuel flow manifold valve plunger (photo courtesy of the NTSB)




Photo 6 - View of fuel flow manifold valve compression spring comparison (photo courtesy of the NTSB)