



Photo 1 – View of damage to right wing (owner)



Photo 2 – Separated section of right wing (owner)