



Photo 1 – N8884 at the accident site. Photo courtesy of the pilot.



Photo 2 – N8884 front-right view, showing the right landing gear assembly. Photo courtesy of the pilot.



Photo 3 – N8884, right-rear view. Photo courtesy of the pilot.



Photo 4 – Right outboard tip and aileron. Photo courtesy of the pilot.



Photo 5 – N8884 at the recovery facility. Photo NTSB.



Photo 6 -N8884 at the recovery facility. Photo NTSB.