



Photo 1 – Airplane at the accident site



Photo 2 – Right wing damage



Photo 3 – Tire, propeller, and wing transfer marks at east runway safety area, taxiway A3



Photo 4 – Tire marks at east runway safety area, taxiway A3



Photo 5 – Wing transfer marks at east runway safety area, taxiway A3



Figure 6 – Propeller blade transfer marks at east runway safety area, taxiway A3