



Photo 1 – View of substantial damage to both wings and fuselage (Courtesy of IIC)



Photo 2 – View of substantial damage to the fuselage (Courtesy of IIC)



Photo 3 – View of propeller and engine impact damage (Courtesy of IIC)