


WPR23FA239

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident engine during exam (courtesy of engine manufacturer)



Photograph 2 - View of exhaust duct with external deformation consistent with torsional energy



Photograph 3 - View of Power Turbine stator housing with environmental debris



Photograph 4 - View of reduction gearbox "A" flange fracture



Photograph 5 - View of a fuel nozzle removed packed with environmental debris