



Joshua Cawthra
Senior Aviation Accident Investigator
Aviation - Western Pacific Region

Date: August 19, 2024

Subject: WPR22FA331

Contact: Ray Anderson - Anderson Aeromotive

During a telephone interview, Mr. Anderson reported that the engine was removed and sent to his company at the request of the customer due to it sitting for a number of years. Mr. Anderson said that upon receipt of the engine in 2022, they removed all of the cylinders, changed the oil control rings, reinstalled the cylinders along with various seals and gaskets. Once the work was complete, they installed the engine on a test stand and ran it at takeoff power for what he recalled, 2 hours. Mr. Anderson stated that the engine ran normal with no issues noted. Once the work was completed, they returned the engine to the customer for installation on the airplane in August, 2022.

- END