

WPR22FA350

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Initial impact point.



Photograph 2 - Engine within the debris path.



Photograph 3 - Wreckage debris area.



Photograph 4 - Recovered wreckage.



Photograph 5 - Recovered wreckage.



Photograph 6 - Recovered wreckage.



Photograph 7 - Accident sequence photo. (Courtesy of A. Taylor)