



Photo 1 – View of damage to the outboard left wing and wingtip (Courtesy of FAA)



Photo 2 – View of damage to the inboard left wing and wing and wing root (Courtesy of FAA)