

WPR22LA060

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damaged left horizontal stabilizer



Photograph 2 - View of damaged right horizontal stabilizer



Photograph 3 - View of airplane and engine prior to ground run



Photograph 4 - View of removed top and bottom spark plugs



Photograph 5 - View of internal components for right had magneto



Photograph 7 - Caption of photograph (Courtesy of XXXX)