

Joshua Cawthra

From: Fritz, Jeffrey W (FAA) [REDACTED]
Sent: Wednesday, April 27, 2022 8:14 AM
To: Cawthra Joshua
Subject: N20617 Cessna 206 in SBA
Attachments: NLG Upper strut Assy IPC.pdf; T206 NLG IPC.pdf; RH Link Rod Assy Pic 2.jpg; RH Link Rod Assy.jpg; RH NLG Trunion Fitting Pic 2.jpg; RH NLG Trunion Fitting Pic 3.jpg; RH NLG Trunion Fitting Pic 4.jpg; RH NLG Trunion Fitting.jpg

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Josh,

Attached are photos of the NLH upper attach point of the trunnion assembly. It has broken and pulled away from the attach point. Also the item covered with the orange sleeve is a link rod assembly which Cessna Technical operations suspects may have failed or stuck. There are two link rod assemblies installed, one on the right and one on the left which connect to the rudder pedals. Photos RH NLG Trunion Fitting Pic 3 & 4 are of the trunnion assembly broken at the attach point.

Feel free to give me a call if you need assistance understanding what the pics are of.

Regards,

Jeffrey W. Fritz
Aviation Safety Inspector, AW



Federal Aviation
Administration

Van Nuys FSDO

[REDACTED]
Van Nuys, CA 91406
[REDACTED]