

WPR22LA166

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane upright in riverbank (Courtesy of recovery company)

HOURS		10ths	DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
09/22				
3/30			N4398B 03/30/2022 hobbs 5673	
22			Replaced oil Philips 20/50 xc and filter leak checked no leaks found. I certify that this aircraft has been inspected in accordance with a annual inspection and was found to be airworthy Paul. Eckert A/P [REDACTED] I/A [REDACTED]	

Photograph 2 - Excerpt of annual inspection entry for the engine



Photograph 3 - View of separated carburetor from impact damage



Photograph 4 - View of removed top spark plugs



Photograph 5 - View of removed right hand magneto



Photograph 6 - View of removed left hand magneto