



Photo 1 –N15MF, showing substantial damage to the left wing and fuselage. Photo courtesy of the pilot.



Photo 2 – N15MF, showing substantial damage to the fuselage. Photo courtesy of the pilot.