




**Photo 1 – N90326 at the accident location. Photo courtesy of the operator.**



**Photo 2 – Front, underside view. Photo courtesy of the operator.**



**Photo 3 – Tail rotor assembly, showing the absence of one tail rotor blade. Photo courtesy of the operator.**



**Photo 4 – Components received by the National Transportation Safety Board’s Materials laboratory.**