



Photo 1 – View of empennage damage (courtesy of the operator)



Photo 2 – Close up view of tailwheel damage (courtesy of the operator)