



Photo 1 – View of damage to main rotor driveshaft (Courtesy of FAA)



Photo 2 – Overview of damage to the horizontal a vertical stabilizers (Courtesy of IIC)