



Photo 1 – Cylinder number 1 and 2 counterweight with two incorrectly installed retaining clips (top right, bottom left).



Photo 2 – Cylinder number 1 and 2 rod caps, bearing and bolt remnants



Photo 3 – Fragments of counterweight, bushings, a single counterweight pin, and four retaining rings and plates