

WPR22LA333

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Accident Site (Courtesy of Unknown Photographer)




Photograph 2 - Collective Grip Twist Throttle Installed (Courtesy of NTSB)



Photograph 3 - Main Rotor Blades (Courtesy of NTSB)



Photograph 4 - Collective Assembly and Throttle Components (Courtesy of Bell Helicopters)



Photograph 5 - Throttle Detent Wear (Courtesy of Bell Helicopters)