



Photo 1 – View of pilot side center pedestal / floorboard damage (Photo courtesy of Clark County DOA)



Photo 2 – View of underside of airplane damage (Photos courtesy of Clark County DOA)