

WPR22LA352

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of nosed over airplane in an open field with damage to tailcone and wings
(Courtesy of Highway Patrol Supervisor)**



Photograph 2 - View of disassembled airplane on a flatbed pick truck (Courtesy of FAA Inspector)



Photograph 3 - View of accident engine (Courtesy of FAA Inspector)



Photograph 4 - View of damaged 3-bladed propeller (Courtesy of FAA Inspector)



Photograph 5 - View of damaged tailcone (Courtesy of FAA Inspector)