



Photo 1 – View of substantial damage to tail boom (provided by pilot)