

WPR23FA073

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the airplane at rest after nose over on shoreline with right wing submerged (Courtesy of LEO)



Photograph 2 - View of inverted airplane -left side (Courtesy of LEO)



Photograph 3 - View of damage to left wing (Courtesy of LEO)



Photograph 4 - View of damage to the right wing (Courtesy of LEO)



Photograph 5 - View of damage to upper and lower engine mounts (Courtesy of IIC)