


WPR23FA141


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aerial view of impact crater and main wreckage (Courtesy of LEA)



Photograph 2 -View of main wreckage as viewed from North to South (Courtesy of IIC)




Photograph 3 - View of main wreckage taken from inside the impact crater (Courtesy of IIC)



Photograph 4 - View of accident site location as viewed from East to West (Courtesy of IIC)



Photograph 5 - View of main wreckage as viewed from North to South (Courtesy of IIC)



Photograph 6 - View from the resting location of the upper 1/3 of the vertical stabilizer and the rudder over 1 mile away from main wreckage (Courtesy of IIC)



Photograph 7 - View of the upper 1/3 of the vertical stabilizer and rudder (Courtesy of IIC)