

WPR23FA258

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Wreckage - Left Side (Courtesy of NTSB)



Photograph 2 - Wreckage and Power Lines (Courtesy of Textron Aviation)



Photograph 3 - Empennage Wrapped with Power Line (Courtesy of Textron Aviation)



Photograph 4 - Propeller and Spinner (Courtesy of Lycoming Engines)