


WPR23LA004

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the accident site (Courtesy of the FAA)



Photograph 2 - View of the tail rotor driveshaft (Courtesy of the FAA)