



Photo 1 – Accident Site (AZ Aerotech Photo)




Photo 2 – Left Wing Damage (AZ Aerotech Photo)