

WPR23LA041

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the initial point of impact being the aft right skid (Courtesy of FAA)



Photograph 2 - View of the damage to the left wing root (Courtesy of FAA)



Photograph 3 - View of damage to left wing root (Courtesy of FAA)



Photograph 4 - View of damage to left wing leading edge and rib (Courtesy of FAA)