



Photo 1 – View of left aileron damage (photo courtesy of pilot)



Photo 2 – view of right wing leading edge damage (photo courtesy of pilot)