



Photo 1 –N458HW front view, showing the damage to the fuselage, tail cone, and main rotor head. Photo courtesy of the operator.



Photo 2 – Front View. Photo courtesy of the operator.