



Photo 1 – View of Wing Strut Damage (Courtesy of Deputy Sheriff)



Photo 2 – View of Rudder and Vertical Stabilizer Damage